



Construction	Luxury Vinyl Tile
Plank Size	241.3 x 1516.8mm
Tiles per Carton	6pcs / 2.20m ²
Total Weight	9050g/m ²
Wearlayer Thickness	0.55mm
Total Thickness	5.0mm
Surface Protection	High Performance PU
Finish	Embossed in Register Mantel Oak 8594 and Vintage Steel 0143 only Embossed
Bevel	4-sided micro-bevel
Micro Scratch Resistance	≤ MSR-A1 (EN 16094) ≤ MSR-B1 (EN 16094)
Slip Resistance	R10 (DIN 51130)
Electrical Propensity	<2kV (EN 1815)
Fire Rating	CRF > 11.0kW/m ² (ISO 9239-1)
Acoustic Insulation	4dB (EN 10140-3)
Dimensional Stability	≤0.15% (ISO 23999)
Thermal Resistance	0.021 (m ² *K/W) (ISO 12667)
Indoor Air Quality	FloorScore® A+ Emissions Eurofins Gold Certified
Underfloor Heating	Suitable, max 27°C
Residual Indentation	< 0.1mm (EN ISO 24343-1)
Colour Fastness	> 6 Grade (ISO 105-B02)
Classifications	Class 23 Domestic Heavy / Class 33 Commercial Heavy/ Class 42 Industrial Medium
Warranties	LVT Warranty 20 Year Residential Warranty 10 Year Commercial Warranty
Environmental	Greentag Certified Environmental Product Declaration GREENGUARD Gold Certification Declare ISO 9001, ISO 45001, ISO 14001
Installation	Please contact Gilt Edge Industries for all adhesive and installation instructions. NB: If recommended adhesive is not used, claims will not be accepted. Must be laid in accordance with AS/NZ Installation Standards.

- For samples, range and warranty details please contact us on 0800 377 753 or belgotex.co.nz
- Specifications are based on averages from manufacturing processes and may vary within normal industry tolerances.
- This product is intended for use solely as an indoor floor covering and is not recommended or sold for any other purpose.
- Use entryway systems outside each entrance to prevent dirt, sand, grit and other substances from being tracked onto floor.
- **Rubber Migration:** Rubber migration (also known as Plasticiser Migration) is a condition that can cause vinyl to discolour. It is caused by rubber or latex products, eg rubber or latex-soled slippers, shoes and rubber backed mats, coming to contact with the vinyl over a constant period of time. It is neither a manufacturing nor an installation fault and therefore is not covered by our warranties.